Nº 11598

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED8/15/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO138	· · · · · · · · · · · · · · · · · · ·
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?Yes	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTORAnnihilation_Wrecking
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.
fol la scale	138 Oak Ave SE 20 ²
	O Boh Ave SE
SIGNED Bill Pappas Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11598

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	08/06/020_	
RECEIVED OF	Annhilation Weeking	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED			
TO TAP CUT OFF	<pre><pre><pre><pre></pre> <pre>sewer on the</pre></pre></pre></pre>	North .	
	AVE. ST. TYPE OF STREET	asphalt	
THE PREMISES BEING LOT NO	, HOUSE NO		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 18.1871 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	Annihilation	,	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.