Nº 11601

٠, ٠

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED10/9/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM85'
HOUSE NO. 3109	PINST MANHOLE DOWN STREAM
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?Yes	
WAS ATTACHED TO MAINYes	NAME OF CONTRACTORJerry's Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	JILDING SERVED. 3109 Costle West Cr -4-1
Not to scole	-45'
	- 12'ф
SIGNED BIT Pappas Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11601

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Λ	/ MASSILLON, OHIO,	\$/7,20_
RECEIVED OF	Countrag	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
REPAIR O TAP CUTOFF	SEWER ON THE	Your h
	YE. TTTYPE OF STREET	24 Ralt
THE PREMISES BEING LOT NO.	7 (,,), HOUSE NO	1 3/09
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	NO. 19.1971 DULY PASSED BY THE CITY (COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		
$\mathcal{M}_{\mathcal{A}}$,	
IAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.