

N^o 11603

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9/24/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 33' from up stream MH

HOUSE NO. 2375

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

SIZE OF PIPE USED 6"

CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Bontrager

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11603

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/12

RECEIVED OF Bontlinger

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE Sanitary

SI

OF Wilmington Ave.

AVE.
ST. TYPE OF STREET 18

THE PREMISES BEING LOT NO. 16259

, HOUSE NO. 2375

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.