Nº 11604

REMARKS \_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED8/21/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	?
HOUSE NO961		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?yes		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Cottrill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.	cut—olf 57' behind curb _B'do
Not to scole	·	961 Tremont sw 57'- 47' - 5
SIGNED July Inspector for City	FILED AT ENGINEER	'S OFFICE

## Nº 11604

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON,	OHIO,		\$, 20
FOR WHICH PERMISSION IS GRANTED _				,
REPAIR TO TAP	SEWER ON THE		Jouts	4
CUTOFF OF	AVE.		11 of that	Lt
THE PREMISES BEING LOT NO.	3/3/	_, HOUSE NO	9	<u>(a 1</u>
VORK TO BE DONE IN ACCORDANCE WI	/ TH ORDINANCE NO. 19.1971 DULY PAS	SED BY THE CITY C	COUNCIL. AND RULES	OF THE
DEPARTMENT OF PUBLIC SERVICE.	<i>1</i> 3			
NAME OF CONTRACTOR	Chethil			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.