

Nº 11606

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/30/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 27'

HOUSE NO. 852

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Miracle Plumbing

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Jeffrey M. King
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11606

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP ____
CUTOFF

SEWER ON THE

OF

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.