

Nº 11609

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8/29/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM .

HOUSE NO. 1270

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN ____yes

NAME OF CONTRACTOR Steve Miller Exc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Jeffrey in King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11609

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/27

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

SI

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**