


Nº 11614

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/3/02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 128'
HOUSE NO. 956
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? No
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR H&W
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11614

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/9, 20

RECEIVED OF Raymond H. H. H. FEE OF \$ 10

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP 2' Diameter SEWER ON THE East SIDE OF 1st St.

OF 1st St. AVE. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 11614, HOUSE NO. 956

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR How

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.