## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED9/19/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	108'	
HOUSE NO. 2810		100	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH		
WAS LATERAL AT CURB?yes			
WAS ATTACHED TO MAIN <u>yes</u>	NAME OF CONTRACTOR	RP Construction	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	BUILDING SERVED.		7610 Turning Leaf
Not to scale		N	10) sop
			, <u>.</u> 24 <sup>-</sup>
	0	108'	
SIGNED My Inspector for City	FILED AT ENGINEER'S	S OFFICE	
REMARKS		***************************************	***************************************

## Nº 11619

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF RECEIVED OF	MASSILLON, OHIO,
FOR WHICH PERMISSION IS GRANTED	
CUTOFF - A A A A A A A A A A A A A A A A A A	OF STREET (12) (12) (12)
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1 DEPARTMENT OF PUBLIC SERVICE.  NAME OF CONTRACTOR	•

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.