FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10/4/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	72'			
HOUSE NO1506	THE TWANTOLL DOWN STILLING				
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB? Yes					
WAS ATTACHED TO MAINYes	NAME OF CONTRACTOR	H&W	1506 Motnut se		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.		—18' 	[]	
Not to scale		~_	46'-		2
			6'- _{K'dp}	72°	— o
				13.11 31 32]
SIGNED Inspector for City	FILED AT ENGINEE	R'S OFFICE			
REMARKS		•			

N° 11626

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	/0/2				
RECEIVED OF		FEE OF \$5				
FOR WHICH PERMISSION IS GRANTED						
CUTOFF	OF STREET	moth and alt				
	, HOUSE NO	1506				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.						
NAME OF CONTRACTOR	· ·					

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.