Nº 11628

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED10/9/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	19'
HOUSE NO320	THE MARKET BOWN OF TEAM	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?Yes	00110 21112 7110 021 111	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	Cottrill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.	19' o
Net is scole		cut-alf
SIGNED BI Papas	FILED AT ENGINEER'S	OFFICE

N^{0} 11628

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON,	OHIO,	FEE OF \$
FOR WHICH PERMISSION IS GRANTED _			
REPAIR TO TAP CUTOFF	SEWER ON THE		ut
OF	AVE. STATYPE OF STREET_	a	Applace
THE PREMISES BEING LOT NO	2511	_, HOUSE NO	320
	, ,		-
WORK TO BE DONE IN ACCORDANCE WIT	TH ORDINANCE NO. 19.1971 DULY PAS	SED BY THE CITY COUNC	CIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	A		
NAME OF CONTRACTOR	Cathreel	<u> </u>	·

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

and the commence of the control of t