

Nº 11633

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/18/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Tapped into MH

HOUSE NO. 814

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11633

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

10/24

RECEIVED OF _____

Waldertbaum

FEE OF \$ _____

1.15

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary
Cable Ch 74

SEWER ON THE _____

North

SI

OF _____

AVE.

ST. TYPE OF STREET _____

Asphalt

THE PREMISES BEING LOT NO. _____

0183

, HOUSE NO. _____

814

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Waldertbaum

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.