Nº 11634

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10/22/02 HOUSE NO. 1986 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM TOPPED INTO MH DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTORMalovite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED. 1986 Triple Crown Cir SE 3'dp -14' 45'- 45'- 9'dp
SIGNED Bill Pappa 5 Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11634

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u> 10/21/02, 20</u> _
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Malavite	A State of the second
TO TAP TO TAP SANTARY	SEWER ON THE	North
OF Triple CLOWA CIT	SEST. TYPE OF STREET	asphalt-
THE PREMISES BEING LOT NO.	6542 , HOUSE NO.	1986
WORK TO BE DONE IN ACCORDANCE WITH ORDINA DEPARTMENT OF PUBLIC SERVICE.	ANCE NO. 19.1971 DULY PASSED BY THE C	TY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR / / A (e	wite	<u>- </u>

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.