

Nº 11644

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11/6/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

102'

HOUSE NO. 2690

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11644

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/06/02, 20

RECEIVED OF _____ FEE OF \$ 30

FOR WHICH PERMISSION IS GRANTED Tissot Excavating Test for

TO REPAIR TAP CUTOFF tap service SEWER ON THE North SIDE

OF Linda Lane 500 AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 116064, HOUSE NO. 21690

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tissot

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.