Nº 11655

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12/2/02 HOUSE NO. 885 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 56' DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	from upstream MH
WAS ATTACHED TO MAIN Yes SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU		Prop. Line Lateral for 883 Seneca NE 2.5' dp
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	MANAGEMENT AND

Nº 11655

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/27, 20_	
FOR WHICH PERMISSION IS GRANTED	
REPAIR TO TAP CUTOFF OF	5
THE PREMISES BEING LOT NO. SSS, HOUSE NO. 7597	_
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.