· \11656\_

REMARKS .

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	-	UP/S MH
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB? Yes  WAS ATTACHED TO MAIN Yes  SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	. NAME OF CONTRACTOR Malavite BUILDING SERVED.	2444 Harsh
	$\bigwedge$	- 30' +4'ap
,		66
SIGNED Bill Papping Inspector for City	FILED AT ENGINEER'S OFFICE	

## Nº 11656

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO,FEE O	/ (3 /20) F\$
FOR WHICH PERMISSION IS GRANTED		***************************************
CUTOFF	ER ON THE	2444
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19. DEPARTMENT OF PUBLIC SERVICE.	.1971 DULY PASSED BY THE CITY COUNÇIL, ANI	D RULES OF THE
NAME OF CONTRACTOR	itt	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.