Nº 11658

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED1/8/03	IF SO, HOW AND LOCATION FROM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAINYesSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	SE
lat to scole	curb g 5th SE
SIGNED My Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 11658

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	<u></u>
RECEIVED OFFEE OF \$	
FOR WHICH PERMISSION IS GRANTED	
REPAIR TO TAP SEWER ON THE MANY TO THE SEWER ON THE	8
CUTOFF  OF	£1.
THE PREMISES BEING LOT NO. 1514, HOUSE NO. 313	7
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES (	OF THE
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.