## Nº 11659

REMARKS -

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED12/11/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
NOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Molovite Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	2390 Urbona 7'dp 4'
SIGNED Bill Pappa 5 Inspector for City	FILED AT ENGINEER'S OFFICE

## Nº 11659

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		MASSILLON, (	OHIO,		<u> </u>
RECEIVED OF	Mulauit	e Elc	aveling	FEE OF \$	
FOR WHICH PERMISSION IS GRA	NTED		<del>`</del>		
REPAIR TO TAP			41		
of Ulan	AVE. ST. TY	PE OF STREET _		1.24 1.1	14-
THE PREMISES BEING LOT NO	$A_{IJ}/A$		HOUSE NO.	13/3	90
WORK TO BE DONE IN ACCORDA DEPARTMENT OF PUBLIC SERVI		9.1971 DULY PASS	i		
NAME OF CONTRACTOR	Dietusy	ikal	Homes		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.