

Nº 11663

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12/18/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 30' from upstream MH

HOUSE NO. 1351

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED *Jeffrey M. King* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11663

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec 17, 20

RECEIVED OF TISCO ETC FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP SEWER ON THE SOUTH SIDE
CUTOFF

OF Berkman Ave. AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 16550, HOUSE NO. 1345
1351

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TISCO ETC

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**