

Nº 11664

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12/23/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 1314

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH -----

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Miracle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

J. Haines

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11664

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/18/02
RECEIVED OF Miracle Plumbing FEE OF \$ 0

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Repair Sewer SEWER ON THE _____ SI
CUTOFF
OF Acropolis Rd SE AVE.
ST. TYPE OF STREET as built

THE PREMISES BEING LOT NO. 12678, HOUSE NO. 1314

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Miracle

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**