

Nº 11665

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12/23/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1314

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Miracle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

J. Haines

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 11665

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

20

RECEIVED OF

Miracle Plumbing

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Repair sanitary

SEWER ON THE

SI

OF

Aradon Rd SE

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

~~12677~~

12677

HOUSE NO.

1310

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Miracle

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.