## **№** 11672

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED3/4/03	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 240'
HOUSE NO	THE MANUEL DOWN OFFICE IN
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTORTissot
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BI	JILDING SERVED.  390 Stortrook  5 22'  -57'  240'
SIGNED In Inspector for City	FILED AT ENGINEER'S OFFICE
D-144 MIAG	

## Nº 11672

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLO	N, OHIO,	
RECEIVED OF	Lesset	FEE (	OF\$
FOR WHICH PERMISSION IS GRANTED		WARRANGE	
REPAIR TO TAP CUTOFF	LANCYSEWER ON THE	lus	£
of Styler	AL. TYPE OF STREET	ass	halt
THE PREMISES BEING LOT NO	15147	, HOUSE NO	390
WORK TO BE DONE IN ACCORDANCE W	ITH ORDINANCE NO. 19.1971 DULY PA	ASSED BY THE CITY COUNCIL, A	ND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	1.		2
NAME OF CONTRACTOR	Just		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.