Nº 11678

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED3/11/03 | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 58' | |
|--|--|----------|
| HOUSE NO212 | - DISTANCE FROM FIRST MANHOLE | |
| SIZE OF PIPE USED | DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? Yes | - | |
| WAS ATTACHED TO MAINYes | NAME OF CONTRACTOR Betz Exc. 212 24th st SE | B' 45' |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF | BOILDING SETVED. | 1 |
| Not to scale | ← | - 60' |
| | 22 | 1-10. |
| | 12 | 2'dp -4' |
| SIGNED BIT Pappa S Inspector for City | FILED AT ENGINEER'S OFFICE | |
| | | |

Nº 11678

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO, | 03/06/93 |
|---|---|---------------------------|
| RECEIVED OF | | FEE OF \$ |
| FOR WHICH PERMISSION IS GRANTED | Betz Excavating | |
| REPAIR TO TAP FOR SANHUS Y | SEWER ON THE | East |
| 001011 | AVE. ST. TYPE OF STREET | |
| THE PREMISES BEING LOT NO. | 15584 , HOUSE NO | 212 |
| WORK TO BE DONE IN ACCORDANCE WITH ORDIN DEPARTMENT OF PUBLIC SERVICE. | NANCE NO. 19.1971 DULY PASSED BY THE CITY | COUNCIL, AND RULES OF THE |
| NAME OF CONTRACTOR | tz Excavating | |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.