Nº 11693

REMARKS \_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-25-03 HOUSE NO 2 900	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6.1  WAS LATERAL AT CURB? 7.5	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	101LDING SERVED.  2800 Autumn AVE NW 1-10- 8'0P-12' -450
SIGNED Bill Pappas Inspector for City	FILED AT ENGINEER'S OFFICE

## Nº 11693

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OH	110. — W	nch 21	20
	\			,
RECEIVED OF	Jernys?	Execupting	7FEE OF \$	
OR WHICH PERMISSION IS GRANTED	same			
REPAIR SOUTHERY	SEWER ON THE	north	`	
CUTOFF	AVE. ST. TYPE OF STREET			
THE PREMISES BEING LOT NO.	6467 H	IOUSE NO	2800	
VORK TO BE DONE IN ACCORDANCE WITH ORDINA	NCE NO. 19.1971 DULY PASSED	D BY THE CITY COUN	ICIL, AND RULES OF	THE
DEPARTMENT OF PUBLIC SERVICE.	10 1	•		
IAME OF CONTRACTOR Jey	rys Excayativ	19		
	1	1		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.