Nº 11703

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED4/22/3	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO2425	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?Yes	
WAS ATTACHED TO MAINYes	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	الاحق الحقاق المالية ا المالية المالية المالي
Not to scole	26'- 45'- 19' 22'-1' 10' 22' 45' 45'
SIGNED W // Inspector for City	45. 13' 6' 6' -45.  FILED AT ENGINEER'S OFFICE
DENTER	

## Nº 11703

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	04/21/0320_
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Jerry's Excavat	Hing
REPAIR TO TAP TAP SUM CUTOFF	SEWER ON THE	west
OF White	AVE.  ST. TYPE OF STREET	as shalt
THE PREMISES BEING LOT NO.		2425
WORK TO BE DONE IN ACCORDANCE WIT DEPARTMENT OF PUBLIC SERVICE.	H ORDINANCE NO. 19.1971 DULY PASSED BY THE CIT	Y COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Jerry's	<u> </u>

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.