

Nº 11705

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/23/03

IF SO, HOW AND LOCATION FROM

HOUSE NO. 1040-1042

FIRST MANHOLE DOWN STREAM _____ --

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1040-1042 Alpha Si Se

Not to Scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11705

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

04/21/03

RECEIVED OF _____

FEE OF \$ _____

5

FOR WHICH PERMISSION IS GRANTED _____

Jerry's Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

East

SI

OF _____

Alpha St NW

AVE.

ST. TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

16153

, HOUSE NO. _____

1040/1042

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.