


Nº 11706

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/24/03 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 40'
HOUSE NO. 207 DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6" DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Holderbaums

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED *Jeffrey M. King* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11706

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 04/22/03

RECEIVED OF _____ FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Holderbaum's

REPAIR TO TAP repair sanitary SEWER ON THE East CUTOFF _____ SI

OF 12th St NW AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 9840, HOUSE NO. 207

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Holderbaum's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.