

11707

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/30/3

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 171'

HOUSE NO. 4587

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR S. Miller Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Inspector

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11707

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 04/22/03

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED S. Miller Excavating

REPAIR TO TAP tap sanitary SEWER ON THE south SIDE
CUTOFF

OF Brightleaf Ave ^{AVE.} ST. TYPE OF STREET as concrete

THE PREMISES BEING LOT NO. 16659 (22) HOUSE NO. 4587

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR S. Miller

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.