

Nº 11710

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11710

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/29 2020

RECEIVED OF Jerry FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP SEWER SEWER ON THE WEST SIDE
CUTOFF 15935

OF WINDY HILL DR AVE. ST. TYPE OF STREET RESIDENTIAL

THE PREMISES BEING LOT NO. 15935, HOUSE NO. 2260

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Day Star

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.