№ 1171	1

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. SIZE OF PIPE USED	FIRST MANHOLE DOWN STREAM
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF	NAME OF CONTRACTOR
THOW BY SINGING THE PARTY OF TH	BUILDING SERVED.
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11711

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

, " <u>,</u>	MASSILLON, OHIO,	/ / >,?;0
RECEIVED OF	<u>) </u>	E OF \$
CUTOFF!	ER ON THE	<u></u>
THE PREMISES BEING LOT NO.	EØE STREET, HOUSE NO	20170
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19. DEPARTMENT OF PUBLIC SERVICE.		AND RULES OF THE
NAME OF CONTRACTOR	1-1	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.