

Nº 11714

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/30/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

135'

HOUSE NO. 2270

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malovite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to Scale

SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11714

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 04/29/03

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED Malavite Excavating

REPAIR TO TAP tap sanitary SEWER ON THE Eas CUTOFF _____ SI

OF Bowling Green Dr. AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 11251, HOUSE NO. 2270

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.