

Nº 11721

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/9/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Goes into MH

HOUSE NO. 2858

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR K Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED Bill Pappas Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11721

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/9, 2000
RECEIVED OF Kenneth Glick FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP See drawing SEWER ON THE South SIDE
CUTOFF See drawing AVE.
OF See drawing ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15317, HOUSE NO. 2858

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR K. Glick

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.