## Nº 11723

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED5/13/03	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED6"	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?Yes	
WAS ATTACHED TO MAINYes	NAME OF CONTRACTOR Jerry's 390 Joshua NW
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	
Not to Scale	-50' 222'-2' B'dp'-2'
SIGNED Bill Pappa 3 Inspector for City	FILED AT ENGINEER'S OFFICE

## $N^{o}$ 11723

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OF	1IO,	5/202
RECEIVED OF	a CA Course	the state of the s	FEE OF \$57
FOR WHICH PERMISSION IS GRANTED		<u> </u>	
REPAIR O TAP CUTOFF	_ SEWER ON THE	<u>""</u>	· · · · · · · · · · · · · · · · · · ·
	AVE. ST. TYPE OF STREET	40	/
THE PREMISES BEING LOT NO		IOUSE NO	390
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19.1971 DULY PASSE	D BY THE CITY COUN	CIL. AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	4)		
Notes This manner of the same and	<u> </u>	1.3!1 A -	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.