

Nº 11726

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/14/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1282

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11726

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, May 14, 20

RECEIVED OF City of Massillon FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP SEWER ON THE SI
CUTOFF

OF AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 16515, HOUSE NO. 1092

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR THOMAS E. CO

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.