

Nº 11728

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/19/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 45' upstream MH

HOUSE NO. 357

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malovite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11728

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

5/16, 20

RECEIVED OF _____

Malavite

FEE OF \$ _____

52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE _____

South

SI

OF _____

Shaw Ave

AVE.

ST. TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

15878

, HOUSE NO. _____

357

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malavite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**