

Nº 11734

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/4/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM --

HOUSE NO. 2415

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

SIZE OF PIPE USED 6"

CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11734

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 05/28/03, 20

RECEIVED OF _____ FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Jerry's Excavating

REPAIR TO TAP tap sanitary SEWER ON THE west SIDE OF Wright State Dr. CUTOFF

OF Wright State Dr. ^{SAVE.} ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15921, HOUSE NO. 2415

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.