

11743

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/10/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 837

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11743

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6-10, 2057

RECEIVED OF Lisat

FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE main east

SI

OF Liberty Ct

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 116496

HOUSE NO. 837

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Rosenberg

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**