

Nº 11746

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/19/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 2545

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH ---


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE ---

REMARKS ---

Nº 11746

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

06/18/03

RECEIVED OF _____

FEE OF \$ _____

54

FOR WHICH PERMISSION IS GRANTED _____

Malavite Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

south

SI

OF _____

Urbana Ave SE

AVE.

ST. TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

16224 (174)

HOUSE NO. _____

2545

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malavite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**