

Nº 11751

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/23/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 92'

HOUSE NO. 2795

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11751

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

06/20/03

RECEIVED OF

FEE OF \$

50.00

FOR WHICH PERMISSION IS GRANTED

Malavite Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE

sanitary south

SIDE

OF

Autumn Ave NW

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

16446 (49)

HOUSE NO.

2795

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malavite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**