

Nº 11753

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/27/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 823

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11753

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

06/20/1203

RECEIVED OF _____

FEE OF \$ _____

50.00

FOR WHICH PERMISSION IS GRANTED _____

Tissot Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

South

SIDE

OF _____

Liberty Court

AVE
ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO. _____

16497

, HOUSE NO. _____

823

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Tissot

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**