


Nº 11754

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/25/03 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 145'
HOUSE NO. 2043
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malavite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11754

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/23 2013

RECEIVED OF Malawite

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE West SIDE
CUTOFF University Community Dr SE AVE. Asphalt
OF _____

THE PREMISES BEING LOT NO. 00899, HOUSE NO. 2013

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.