Nº 11756

REMARKS _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25-03 HOUSE NO 2053	IF SO, HOW AND LOCATION FROM 26 1
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTORMalavite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	
	1-2
	1 45° -8' Down
	45° 6'DP (" wye 91'wye " .26'
SIGNED Bill Pappas Inspector for City	FILED AT ENGINEER'S OFFICE
inspector for only	

Nº 11756

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MA	SSILLON, OHIO,	6/30.	3
RECEIVED OF Malauite	· · · · · · · · · · · · · · · · · · ·	FEE OF \$	50
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP SEWER ON CUTOFF AVE.	,		_ SIDE
OF Mulling Chances TXPEOFS	THEET /	MARIE LA	
THE PREMISES BEING LOT NO. J 0 6 8 9 9	, HOUSE NO	2053	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 [OULY PASSED BY THE CITY COU	INCIL, AND RULES OF THE	Ē
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.