

Nº 11760

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/23/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2842

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Johns Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11760

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/26, 200

RECEIVED OF

John's Excavating

FEE OF \$

50.00

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sanitary
Autumn Ave. NW

SEWER ON THE

North

SIDE

OF

AVE.

TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

16463

, HOUSE NO.

2842

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Klatt Homes

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**