Nº 11767

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED6	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	cut-off
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Cottrill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.
Not to Scale	1227 9th St SW -105'
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11767

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,		<u>_07/15/03</u> , ₂₀	
RECEIVED OF	0 4 4		FEE OF \$	15.0
OR WHICH PERMISSION IS GRANTED _	Cottrill	Wrecking		<u> 11111-lu</u> v
REPAIR O TAP CUTOFF	Sanitary sewer on the	<u>- Sankan</u>	west	SIDE
9th 51	AVE. ST. TYPE OF STREET	0	sphalt	
HE PREMISES BEING LOT NO.	06 288	, HOUSE NO	/32	7
VORK TO BE DONE IN ACCORDANCE W	ITH ORDINANCE NO. 19.1971 DULY PA	SSED BY THE CITY (COUNCIL, AND RULES	OF THE
DEPARTMENT OF PUBLIC SERVICE.	Cottrill	0.40	And the control of th	MANAGARAN Managaran Managaran
V.III.E 01 00.11.1.11.10.10.11				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.