

No 1922

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected Aug. 12, 1925House No. Lat 98. 3569.

927

7032

Size of pipe used 6 inchIf so how and location from
first manhole down stream202 feet from Main Hole BATHDistance from first manhole
down stream to ditch at
curb line and depth209 feet 7 feetWas lateral at curb? YesWas attached to main YesName of Contractor C. H. Hunt

Show by diagram relation of lateral to wall of building served.

13-17 inches from
South Corner
of Main Building



Signed

Mr. Heshore

Inspector for City

Filed at Engineer's Office

AUG 13 1925

Remarks

8-6. Y. insert

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1922

PERMIT TO TAP SEWER

Massillon, O.,

1922

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 3569
-St.

House No.

Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor