

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1924

Date Inspected Aug. 22, 1925

If so how and location from
first manhole down stream

House No. 428 266

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

34 feet from Main Hole south 7 feet deep

Was lateral at curb? yes


Name of Contractor

Julius Mittman

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

19 feet from North West
corner the Main
Building
6-6. Deep.



Signed

Wm. Deaton
Inspector for City

Filed at Engineer's Office

8/26/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1924

PERMIT TO TAP SEWER

Massillon, O., Aug 13 19

Received of John W. Hutton fee of \$ 2.01

for which permission is granted to tap

Sanitary sewer, on the East side

of Independence Ave., the premises being Lot No. 2117 St.

House No. 266 426 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor J. W. Hutton