

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1926

Date Inspected Aug. 24, 1925

If so how and location from
first manhole down stream

House No. 484 274

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 inch

4 ft. from Main Hole with 4 feet Deep

Was lateral at curb? yes


Name of Contractor

Was attached to main yes

Julius Wittman

Show by diagram relation of lateral to wall of building served.

12 inch from both feet
corner Main Building
6-6 inches Deep



Signed

Wm. D. Dushane
Inspector for City

Filed at Engineer's Office

8/25/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1926

PERMIT TO TAP SEWER

Massillon, O.,

Aug 13 1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 274
St.

House No. 759

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor