

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 1929

Date Inspected Aug. 17, 1925

House No. Lot 34587420

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

If so how and location from
first manhole down stream


Distance from first manhole
down stream to ditch at
curb line and depth

Name of Contractor

69 feet from Main Hole. Street 7 feet deep.

A. Mantone

17 feet from
West Park. Ditch
7 feet deep.



Signed

Wm. Bushon
Inspector for City

Filed at Engineer's Office

AUG 18 1925

Remarks

~~Recd~~

69 feet east of manhole at 6th St

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1929

PERMIT TO TAP SEWER

Massillon, O., Aug 14 192

Received of Antonio Mastromi fee of \$ 2.00

for which permission is granted Ralph Schieber

to tap San sewer, on the South side

of Rotch Ave., the premises being Lot. No. 3758
St. 7420

House No. 1009 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Mastromi