

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No 1933

4-13

Date Inspected Aug. 19, 1925

If so how and location from
first manhole down stream

House No. 811 451

Size of pipe used 6 inch

Distance from first manhole
down stream to ditch at
curb line and depth 4 feet deep


Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served

East corner
on Main
Building
7 foot deep



Signed

Wm. Desbrow
Inspector for City

Filed at Engineer's Office

AUG 19 1925

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1933

PERMIT TO TAP SEWER

Massillon, O., _____ 19__

Received of Antonio's Masonry fee of \$ 2.00

for which permission is granted Chas H Ammons

to tap San sewer, on the South side

of Cherry Ave, the premises being Lot. No. St 06
451 811 9745 44
St.

House No. 811. Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor A. Masoni