

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 1934

Date Inspected Aug. 24, 1925

House No. Lot No. 396240

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

11 - 8 feet from
North East corner
this Building
Depth 6 - 8.


If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

12.9 feet from Man Hole East 6 - 6 Depth

Name of Contractor

John Rist



Signed

Mr. Deakon
Inspector for City

Filed at Engineer's Office

8/25/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 1934

PERMIT TO TAP SEWER

Massillon, O.,

Aug 19th 1925

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor