

Nº 1937

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Date Inspected Aug. 22, 1925

House No. 1801

Size of pipe used 6 inch

Was lateral at curb? yes

Was attached to main yes

Show by diagram relation of lateral to wall of building served.

21 feet from south
corner Main
Building
4-6 ft. deep.


If so how and location from
first manhole down stream

Distance from first manhole
down stream to ditch at
curb line and depth

68-8 feet from Man Hole first, 4 feet deep

Name of Contractor

Julius Wittman



Signed

Wm. Desbrow

Inspector for City

Filed at Engineer's Office

Pluffert
2 curbs

8/26/25

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 1937

PERMIT TO TAP SEWER

Massillon, O.,

Aug 20th 1945

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

side

of

Ave., the premises being Lot. No. 2126
St. 3450

House No. 1801

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor